

CORROLESS CCI 400

CORROSION INHIBITOR (WAX COATING)

DESCRIPTION A blend of waxes and vapour phase corrosion inhibitor (VCI), developed for

outdoor use under aggressive conditions. This product is also available in aerosol cans as CCI 400A, when volume solids, drying times etc. may vary from

values given in this data sheet.

PRODUCT FEATURES AND RECOMMENDED USES • Works by both contact and vapour phase inhibition.

- Suitable for application onto damp surfaces.
- Gives up to 4 years protection depending on environment.
- Easily removed or recoated.
- Applications include equipment, void spaces, structural steel, winches, wire ropes, cranes, box sections etc.

TECHNICAL DATA

Volume Solids (±2%) 55%.

Specific gravity 0.9 kg/litre.

Film thickness Wet Film 182 microns. Dry Film 100 microns.

Mixing Ratio Single pack.

Theoretical Coverage 5.5 m²/litre. Practical coverage rate can vary depending on application method,

temperature, profile and porosity of the substrate.

Pot Life (at 18°C) Not applicable.

Drying Time (at 18°C)

at recommended dft

Dries to a wax finish in 24 hours.

Thinners and

Cleaning Solvent Corroless Thinners No 2. (Solvent Gun Wash may be used for cleaning only).

Finish Dull wax.

Colours Semi-translucent light brown.

Storage Store in dry, cool conditions and protect from frost.

CORROLESS Corrosion Control, Worldwide Headquarters, Kelvin Way, WEST BROMWICH, West Midlands B70 7JZ,

Telephone: Fax: Web: e-mail:

+44 (0)121 524 2235 +44 (0)121 553 2787 www.corroless.com contact@corroless.com



CORROLESS CCI 400

CORROSION INHIBITOR (WAX COATING)

APPLICATION DETAILS

Recommended substrate Steel and most other metallic substrates.

Surface PreparationNo special surface preparation is required, but the cleaner the substrate, the

more effective will be the protection achieved from the product. For best results degrease using a water soluble degreaser and prepare heavily corroded steel surfaces using rust scrapers, wire brushes, needle guns, etc. to St2 standard of EN ISO 8501-1:1988 or equivalent. Wash down with fresh water and allow to

dry prior to application.

For clean surfaces (e.g. production components, machinery casings etc.) degrease using a water soluble degreaser to remove dirt and oil/grease

deposits and allow to dry prior to application.

Application

Method	Airless Spray	Conventional Spray	Brush	Roller
Output Fluid Pressure	3000 psi	Yes – thinning	Yes	No
Tip size	13-17 thou	required		
Fan angle	50°			

Spray For conventional spray up to 10% Corroless Thinners No.2 should be added.

Brush Apply unthinned, lay on, do not over brush.

Mixing Stir thoroughly before use.

Application Temperature 2°C to 35°C.

Ambient Conditions Only apply in conditions of good ventilation, which should be maintained during

drying. Do not apply when rain, mist, sleet or snow are imminent. During application and drying time the Relative Humidity should not exceed 85% and

the steel temperature should remain at least 3°C above the dew point.

Stripe coat Stripe coat all sharp edges, bolts, rivets, welds etc.

Flash Point 32 - 55°C.

Health and Safety At all times observe precautionary notices on containers. Refer to Material

Safety Data Sheet available from Corroless on request.